

# Slice test report – L1Topo

## Tests with all FEXes

- gFEX: CRC and data corruption issues understood and fixed: data being transmitted now error-free and stable
- jFEX: no new/different results wrt previous slice test
- eFEX: cause of CRC mismatch has been identified.  
No new tests with revised firmware yet
- Integration with TTC data reception code failed

No final combined run with concurrent readout of all FEXes

# Plans

Before next slice test week have a go at:

1. Double check CRC for eFEX data
2. Finally integrate play/spy circuitry with TTC data to synchronize spy data to BCreset
3. Integrate with readout circuitry (Marek)
4. Make some progress on software integration